

**Dennis R. Madison**  
Vice President - Hatch

**Southern Nuclear  
Operating Company, Inc.**  
Plant Edwin I. Hatch  
11028 Hatch Parkway North  
Baxley, Georgia 31513  
  
Tel 912.537.5859  
Fax 912.366.2077



August 10, 2009

Docket No.: 50-366

NL-09-1221

U. S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, D. C. 20555-0001

Edwin I. Hatch Nuclear Plant  
Licensee Event Report  
Turbine Trip On High Reactor Water Level  
Due To Failed Circuit Board Results in Reactor Scram

Ladies and Gentlemen:

In accordance with the requirements of 10 CFR 50.73(a)(2)(iv)(A), Southern Nuclear Operating Company is submitting the enclosed Licensee Event Report (LER) concerning a reactor scram resulting from a turbine trip due to high reactor water level.

This letter contains no NRC commitments. If you have any questions, please advise.

Sincerely,

A handwritten signature in black ink, appearing to read "Dennis R. Madison".

D. R. Madison  
Vice President – Hatch

DRM/MJK/

Enclosure: LER 2-2009-004

cc: Southern Nuclear Operating Company  
Mr. J. T. Gasser, Executive Vice President  
Ms. P. M. Marino, Vice President – Engineering  
RTYPE: CHA02.004

U. S. Nuclear Regulatory Commission  
Mr. L. A. Reyes, Regional Administrator  
Mr. R. E. Martin, NRR Project Manager – Hatch  
Mr. J. A. Hickey, Senior Resident Inspector – Hatch

## LICENSEE EVENT REPORT (LER)

Estimated burden per response to comply with this mandatory collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records and FOIA/Privacy Service Branch (T-5 F52), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

|   |                               |                   |
|---|-------------------------------|-------------------|
| 1. FACILITY NAME<br>Edwin I. Hatch Nuclear Plant Unit 2 | 2. DOCKET NUMBER<br>05000 366 | 3. PAGE<br>1 OF 4 |
|---|-------------------------------|-------------------|

4. TITLE  
Turbine Trip On High Reactor Water Level Due To Failed Circuit Board Results in Reactor Scram

| 5. EVENT DATE |     |      | 6. LER NUMBER |                   |         | 7. REPORT DATE |     |      | 8. OTHER FACILITIES INVOLVED |               |
|---------------|-----|------|---------------|-------------------|---------|----------------|-----|------|------------------------------|---------------|
| MONTH         | DAY | YEAR | YEAR          | SEQUENTIAL NUMBER | REV NO. | MONTH          | DAY | YEAR | FACILITY NAME                | DOCKET NUMBER |
| 06            | 23  | 2009 | 2009          | - 004 -           | 0       | 08             | 10  | 2009 | FACILITY NAME                | DOCKET NUMBER |
|               |     |      |               |                   |         |                |     |      |                              | 05000         |
|               |     |      |               |                   |         |                |     |      |                              | 05000         |

|                            |  |                                     |  |   |  |   |  |   |  |   |  |  |  |   |                                      |  |  |  |  |   |   |   |  |  |  |  |  |   |   |   |   |   |                                      |                                      |
|----------------------------|--|-------------------------------------|--|---|--|---|--|---|--|---|--|--|--|---|--------------------------------------|--|--|--|--|---|---|---|--|--|--|--|--|---|---|---|---|---|--------------------------------------|--------------------------------------|
| 9. OPERATING MODE<br><br>1 | 11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR§: (Check all that apply) |                                     |  |   |  |   |  |   |  |   |  |  |  |   |                                      |  |  |  |  |   |   |   |  |  |  |  |  |   |   |   |   |   |                                      |                                      |
|                            | <input type="checkbox"/> 20.2201(b)  | <input type="checkbox"/> 20.2201(d) | <input type="checkbox"/> 20.2203(a)(1) | <input type="checkbox"/> 20.2203(a)(2)(i) | <input type="checkbox"/> 20.2203(a)(2)(ii) | <input type="checkbox"/> 20.2203(a)(2)(iii) | <input type="checkbox"/> 20.2203(a)(2)(iv) | <input type="checkbox"/> 20.2203(a)(2)(v) | <input type="checkbox"/> 20.2203(a)(2)(vi) | <input type="checkbox"/> 20.2203(a)(3)(i) | <input type="checkbox"/> 20.2203(a)(3)(ii) | <input type="checkbox"/> 20.2203(a)(4) | <input type="checkbox"/> 50.36(c)(1)(i)(A) | <input type="checkbox"/> 50.36(c)(1)(ii)(A) | <input type="checkbox"/> 50.36(c)(2) | <input type="checkbox"/> 50.46(a)(3)(ii) | <input type="checkbox"/> 50.73(a)(2)(i)(A) | <input type="checkbox"/> 50.73(a)(2)(i)(B) | <input type="checkbox"/> 50.73(a)(2)(i)(C) | <input type="checkbox"/> 50.73(a)(2)(ii)(A) | <input type="checkbox"/> 50.73(a)(2)(ii)(B) | <input type="checkbox"/> 50.73(a)(2)(iii) | <input checked="" type="checkbox"/> 50.73(a)(2)(iv)(A) | <input type="checkbox"/> 50.73(a)(2)(v)(A) | <input type="checkbox"/> 50.73(a)(2)(v)(B) | <input type="checkbox"/> 50.73(a)(2)(v)(C) | <input type="checkbox"/> 50.73(a)(2)(v)(D) | <input type="checkbox"/> 50.73(a)(2)(vii) | <input type="checkbox"/> 50.73(a)(2)(viii)(A) | <input type="checkbox"/> 50.73(a)(2)(viii)(B) | <input type="checkbox"/> 50.73(a)(2)(ix)(A) | <input type="checkbox"/> 50.73(a)(2)(x) | <input type="checkbox"/> 73.71(a)(4) | <input type="checkbox"/> 73.71(a)(5) |
| 10. POWER LEVEL<br><br>061 | Specify in Abstract below or in NRC Form 366A  |                                     |  |   |  |   |  |   |  |   |  |  |  |   |                                      |  |  |  |  |   |   |   |  |  |  |  |  |   |   |   |   |   |                                      |                                      |

## 12. LICENSEE CONTACT FOR THIS LER

|   |  |
|---|--|
| FACILITY NAME<br>Edwin I. Hatch / Steve Tipps, Principal Licensing Engineer | TELEPHONE NUMBER (Include Area Code)<br>912-537-5880 |
|---|--|

## 13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

| CAUSE | SYSTEM | COMPONENT | MANUFACTURER | REPORTABLE TO EPIX | CAUSE | SYSTEM | COMPONENT | MANUFACTURER | REPORTABLE TO EPIX |
|-------|--------|-----------|--------------|--------------------|-------|--------|-----------|--------------|--------------------|
| B     | SJ     | LC        | Y006         | Y                  |       |        |           |              |                    |

## 14. SUPPLEMENTAL REPORT EXPECTED

☐ YES (If yes, complete 15. EXPECTED SUBMISSION DATE) ☒ NO

## 15. EXPECTED SUBMISSION DATE

| MONTH | DAY | YEAR |
|-------|-----|------|
|-------|-----|------|

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On June 23, 2009 at 03:51 EDT, Unit 2 was in mode 1 with an approximate reactor power of 1710 CMWTh. At this time an automatic reactor scram occurred as a result of a turbine trip due to high reactor water level. Prior to the event the reactor was increasing in power during startup from a recent outage. An instrument which controls reactor water level failed resulting in an increase in reactor water level. The water level increased to a point where the turbine control valve fast closure trip signal was initiated due to high reactor water level. All control rods fully inserted and Reactor Feed pumps tripped. Reactor water level initially decreased to approximately negative 25 inches, due to void collapse. The Primary Containment isolation Valve Group 2 isolation setpoint was reached, and the Group 2 valves isolated. Both the 'A' and 'B' Reactor Feed Pumps initially tripped, and the 'A' feed pump was restarted and used to restore and maintain reactor water level. Reactor pressure reached an upper value of approximately 964 psig. No Safety Relief Valves opened, nor were they required to open, based on the maximum pressure reached. Reactor water level increased to a maximum value of approximately 60 inches above instrument zero, but was restored to normal range.

The cause of this event was the failure of an internal power supply electrolytic capacitor which caused a failure of the DC power supply for the Yokogawa level controller 2C32-K648.

The failed power supply card containing the capacitor was replaced following the event and repetitive tasks have been created to replace this and similar power supply cards at a prescribed interval.

LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET

| 1. FACILITY NAME                    | 2. DOCKET | 6. LER NUMBER |                      |                    | 3. PAGE |      |
|-------------------------------------|-----------|---------------|----------------------|--------------------|---------|------|
| Edwin I. Hatch Nuclear Plant Unit 2 | 05000366  | YEAR          | SEQUENTIAL<br>NUMBER | REVISION<br>NUMBER | 2       | OF 4 |
|                                     |           | 2009          | - 004                | - 0                |         |      |

**NARRATIVE** (If more space is required, use additional copies of NRC Form 366A)PLANT AND SYSTEM IDENTIFICATION

General Electric - Boiling Water Reactor

Energy Industry Identification System codes appear in the text as (EIS Code XX).

DESCRIPTION OF EVENT

On June 23, 2009 at 03:51 EDT, Unit 2 was in mode 1 with an approximate reactor power of 1710 CMWTh. At this time an automatic reactor scram from a turbine (EIS Code TA) trip due to high reactor water level occurred. Prior to the event the reactor was increasing in power during startup from a recent outage. At approximately 03:40 EDT, the 2C32-K648 median controller (EIS Code SJ) failed and no longer tracked actual reactor water level. This controller provides input for the indicated level on the plasma display (EIS Code SJ) and the 2C32-R600 feedwater master controller (EIS Code SJ). Reactor water level began to decrease approaching 30 inches as shown by Safety Parameter Display System (SPDS, EIS Code IU) data however the plasma panel did not indicate this change in level. Reactor water level then began to increase. The High Pressure Coolant Injection (HPCI, EIS Code BJ) and Reactor Core Isolation Cooling (RCIC, EIS Code BN) High Reactor Water Level Trip alarms were received. Approximately 30 seconds after receiving the alarm the turbine tripped on the turbine control valve (EIS Code TA) fast closure trip signal due to high reactor water level. All control rods fully inserted (EIS Code JD) and Reactor Feed pumps (RFP, EIS Code SJ) tripped. Reactor water level initially decreased to approximately negative 25 inches, due to void collapse. Primary Containment isolation Valve Group 2 (EIS Code JM) isolation setpoint was reached and the Group 2 valves isolated. Both the 'A' and 'B' Reactor Feed Pumps initially tripped, and the 'A' feed pump was restarted and used to restore and maintain reactor water level. Reactor pressure reached an upper value of approximately 964 psig. No Safety Relief Valves (SRVs, EIS Code SB) opened, nor were they required to open, based on the maximum pressure reached. Reactor water level increased to a maximum value of approximately 60 inches above instrument zero but was restored to normal range.

CAUSE OF EVENT

The cause of this event was the failure of an internal power supply electrolytic capacitor on the power supply board which caused a failure of the DC power supply for the Yokogawa level controller 2C32-K648.

During recovery efforts it was determined that the 2C32-K648 controller was not responding to reactor water level increases and was displaying the error code P.error. Per the Yokogawa vendor manual, this is indicative of an internal power supply failure. The P.error code was intermittently displayed during the recovery process.

The controller was removed from service and transported to the Maintenance lab for analysis. Power was applied to the controller, and the P.error code was again displayed. This error was intermittent during the analysis period. Internal inspection of the power supply identified a failed electrolytic capacitor.

**LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET**

| 1. FACILITY NAME                    | 2. DOCKET | 6. LER NUMBER |                      |                    | 3. PAGE |
|-------------------------------------|-----------|---------------|----------------------|--------------------|---------|
| Edwin I. Hatch Nuclear Plant Unit 2 | 05000366  | YEAR          | SEQUENTIAL<br>NUMBER | REVISION<br>NUMBER | 3 OF 4  |
|                                     |           | 2009          | - 004                | - 0                |         |

**REPORTABILITY ANALYSIS AND SAFETY ASSESSMENT**

This event is reportable per 10 CFR 50.73(a)(2)(iv)(A) because unplanned actuations of a safety feature system listed in 10 CFR 50.73 occurred. In this instance, a reactor protection system (RPS) actuation resulted in a reactor scram. The reactor protection system (EIS Code JC) actuated on turbine control valve fast closure when a high reactor water level was sensed.

Fast closure of the turbine control valves is initiated when a reactor high water level condition exists. The turbine control valves close as rapidly as possible to prevent water intrusion into the main steam lines. Valve closing causes a sudden reduction in steam flow that, in turn, results in a reactor vessel pressure increase. If the pressure increases to the pressure relief setpoints, some or all of the SRVs will briefly discharge steam to the suppression pool (EIS Code BL). In this event the reactor pressure did not reach corresponding setpoint of the SRVs.

Reactor scram and recirculation pump (EIS Code AD) trip initiation by turbine control valve fast closure prevents the core from exceeding thermal hydraulic safety limits following a main generator or main turbine trip. A reactor scram is initiated on turbine control valve fast closure. The scram, along with the reactor recirculation pump trip system, ensures that the minimum critical power ratio safety limit is not exceeded.

The recirculation pump trip system, upon sensing a turbine control valve fast closure, trips the reactor recirculation pumps resulting in a decrease in core flow. The rapid core flow reduction increases void content and reduces reactivity in conjunction with the reactor scram to reduce the severity of the transients caused by the turbine trip.

In this event, the main turbine tripped as designed in response to the sensed power load unbalance. The turbine trip actuated the reactor protection system and scrammed the reactor. Vessel water level was maintained well above the top of the active fuel throughout the transient. The water level decrease was terminated prior to reaching the automatic initiation set point for HPCI and RCIC. Operations restarted the 'A' feed pump immediately following the reactor scram and subsequent feed pump trip. This pump was used to restore and maintain reactor water level. Therefore no safety system actuations on low water level, including emergency core cooling systems, were automatically initiated nor were any required.

Based on this analysis, it is concluded that this event had no adverse impact on nuclear safety.

**CORRECTIVE ACTIONS**

The 2C32-K648 controller was replaced.

Repetitive Tasks have been created to replace the power supply for this and similar controllers at a prescribed interval.

A new subsection was added to maintenance procedures 57CP-CAL-226-1 and 57CP-CAL-226-2 to provide instructions for replacement of the Yokogawa power supplies

**LICENSEE EVENT REPORT (LER)**  
**CONTINUATION SHEET**

U.S. NUCLEAR REGULATORY COMMISSION

| 1. FACILITY NAME                    | 2. DOCKET | 6. LER NUMBER |                      |                    | 3. PAGE |
|-------------------------------------|-----------|---------------|----------------------|--------------------|---------|
|                                     |           | YEAR          | SEQUENTIAL<br>NUMBER | REVISION<br>NUMBER |         |
| Edwin I. Hatch Nuclear Plant Unit 2 | 05000366  | 2009          | - 004                | - 0                | 4 OF 4  |

ADDITIONAL INFORMATION

Other Systems Affected: None

Failed Components Information:

Master Parts List Number: 2C32-K648

Manufacturer: Yokogawa (Y006)

Model Number: SCMS-100\*E/NPR/MTS/HTB

Type: Level Controller

EIIS System Code: SJ

Reportable to EPIX: Yes

Root Cause Code: B

EIIS Component Code: LC

Commitment Information:

This report does not create any new permanent licensing commitments.

Previous Similar Events:

There are no similar events within the past two years in which a power supply card failure occurred on a reactor water level control instrument.